



AGC Glass-Kingsport Plant-SKV/GKT-Spill Investigation-8/6/12

PVC Line Break Location (Building No. 43)

Flow entering trench



Flow in trench toward basement

Flow on basement floor



Sump pump in trench

Sump pump line





AGC Glass-Kingsport Plant-Spill Investigation-SKV/GKT-8/6/12

Ditch toward outfall SW2



Flow in ditch/pH sample location



Culvert blocked with sediment and trash



Flow entering culvert



Outfall SW2-blocked with sediment



Rear of Building No. 43-no flow coming out